FEDERAL COMMUNICATIONS COMMISSION
445 TWELFTH STREET SW
WASHINGTON DC 20554

MEDIA BUREAU
AUDIO DIVISION
APPLICATION STATUS: (202) 418-2730
HOME PAGE: www.fcc.gov/mb/audio/

ENGINEER: CHARLES N. (NORM) MILLER
TELEPHONE: (202) 418-2767
FACSIMILE: (202) 418-1410
E-MAIL: charles.miller@fcc.gov

June 30, 2009

Gregory L. Masters, Esq.
Wiley Rein LLP
1776 K Street NW
Washington, DC 20006

Re: KFCD (AM), Farmersville, Texas
Facility Identification Number: 43757
Bernard Dallas LLC
Special Temporary Authorization

Dear Counsel:

This is in reference to the request filed December 9, 2008, on behalf of Bernard Dallas LLC ("BDL"). BDL requests extension of the special temporary authority ("STA") granted on June 19, 2008, to operate Station KFCD with parameters at variance and/or reduced power while maintaining monitor points within licensed limits.[1] In support of the request, BDL states that it has installed an STL antenna on one of the station's towers. BDL requests STA pending the filing of an application for direct measurement of operating power.

Requests for extension of STA will be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.

Our review indicates that the licensee has made progress toward restoration of licensed operation, but additional time is required for completing the work. Thus, extension of STA is warranted.

Accordingly, the request for extension of STA IS HEREBY GRANTED. Station KFCD may continue to operate with parameters at variance and/or reduced power while maintaining monitor

[1] KFCD is licensed for operation on 990 kHz with 7 kilowatts daytime and 0.92 kilowatt nighttime, employing different directional patterns daytime and nighttime (DA-2-U).

points within licensed limits. It will be necessary to further reduce power or cease operation if complaints of interference are received. BDL must notify the Commission when licensed operation is restored.[2] BDL must use whatever means are necessary to protect workers and the public from exposure to radio frequency radiation in excess of the Commission's exposure guidelines. *See* 47 CFR § 1.1310.

This authority expires on **December 30, 2009**.

Sincerely,

Charles N. Miller, Engineer
Audio Division
Media Bureau

cc: Bernard Dallas LLC

[2] *See* 47 CFR §§ 73.45(c), 73.51, 73.54, 73.61(b).