# FEDERAL COMMUNICATIONS COMMISSION
## 445 TWELFTH STREET SW
## WASHINGTON DC 20554

**MEDIA BUREAU**
**AUDIO DIVISION**
**APPLICATION STATUS:** (202) 418-2730
**HOME PAGE:** www.fcc.gov/mb/audio/

**ENGINEER:** CHARLES N. (NORM) MILLER
**TELEPHONE:** (202) 418-2767
**FACSIMILE:** (202) 418-1410
**E-MAIL:** charles.miller@fcc.gov

August 29, 2007

Marissa G. Repp, Esq.
Hogan & Hartson, LLP
555 Thirteenth Street NW
Washington, DC 20004-1109

Re: WEAV(AM), Plattsburgh, New York
Facility Identification Number: 52806
CC Licenses, LLC
Special Temporary Authorization

Dear Counsel:

This is in reference to the request filed December 19, 2006, on behalf of CC Licenses, LLC ("CCL"). CCL requests extension of the special temporary authority ("STA") granted September 19, 2006, to operate Station WEAV with parameters at variance from licensed values and/or reduced power while maintaining monitor points within licensed limits.[1] In support of the request, CCL states that it has resolved ground system issues; however, a monitor point issue remains under investigation.

Requests for extension of STA will be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.

Our review indicates that the licensee has made progress toward restoration of licensed operation, but additional time is required for completing the work. Thus, extension of STA is warranted.

---

[1] WEAV is licensed for operation on 960 kHz with 5 kilowatts daytime and 5 kilowatts nighttime, employing different directional antenna patterns daytime and nighttime (DA-2-U).

Accordingly, the request for extension of STA IS HEREBY GRANTED. Station WEAV may continue to operate with parameters at variance from licensed values and/or reduced power while maintaining monitor points within licensed limits. It will be necessary to further reduce power or cease operation if complaints of interference are received. CCL must notify the Commission when licensed operation is restored.[2] CCL must use whatever means are necessary to protect workers and the public from exposure to radio frequency radiation in excess of the Commission's exposure guidelines. *See* 47 CFR § 1.1310.

This authority expires on **February 29, 2008**.

Sincerely,

Charles N. Miller, Engineer
Audio Division
Media Bureau

cc: CC Licenses, LLC

[2] *See* 47 CFR §§ 73.45(c), 73.51, 73.54, 73.61(b).