FEDERAL COMMUNICATIONS COMMISSION
445 12th Street, S.W.
WASHINGTON DC 20554

MEDIA BUREAU
AUDIO DIVISION
TECHNICAL PROCESSING GROUP
APPLICATION STATUS: (202) 418-2730
HOME PAGE: www.fcc.gov/mb/audio/

PROCESSING ENGINEER: Joe Szczesny
TELEPHONE: (202) 418-2700
FACSIMILE: (202) 418-1410
MAIL STOP: 1800B3
INTERNET ADDRESS: Joseph.Szczsny@fcc.gov

MAR 24 2009

John W. Zucker, Assistant Secretary
RD San Francisco Assets, LLC
77 West 66th Street
New York, NY 10023-6298

In re: RD San Francisco Assets, LLC (RDSFA)
KMKY(AM), Oakland, CA
Facility Identification Number: 96
File Number: BZ-20080819ABS

Dear Mr. Zucker:

This is in reference to the above-captioned direct measurement of power application filed by RDSFA to update the antenna monitor; and the February 23, 2009, amendment.

A preliminary review of the amended application indicates that the recently measured NAD83 coordinates for all three towers given in the amendment were not input into the tower registration database to update the locations, therefore this must be corrected by going to the FCC's Wireless Telecommunication's Bureau web site http://wireless.fcc.gov/antenna. and updating all three registration records.

Accordingly, further action on the subject application will be withheld for a period of thirty (30) days from the date of this letter. Failure to amend or respond within the given time period will result in the dismissal of the application pursuant to 47 C.F.R. § 73.3568.

Sincerely,

Son Nguyen
Supervisory Engineer
Audio Division
Media Burea

cc: Lyndon H. Willoughby