

From: B. W. St. Clair [stcl@comcast.net]
Sent: Thursday, April 30, 2009 4:48 PM
To: Mohammad Habib
Subject: Corrected Pages K04QM and K05MC

Attachments: STA_K04QM&K05MC Corrected Pages.pdf
Mohammad: Attached are corrected engineering pages for the STA's for K04QM and K05MC. We inadvertently put the wrong ERP on these applications. The correct output power should be 0.110 kW.

These are digital channels with simple masks and 0.025kW Transmitter Output power.

If you have any other questions please let us know.

Susan Hansen for...

B. W. St. Clair
2355 Ranch Drive
Westminster, CO 80234
303-465-5742
303-465-4067 fax
stcl@comcast.net