



Federal Communications Commission  
Washington, D.C. 20554

May 12, 2015

DTV America II, LLC  
12717 W Sunrise Blvd., Suite 372  
Sunrise, FL. 33323

1800E3-RLG

In re: Low Power Television Application of:  
DTV America II, LLC  
Channel 43, Canton, OH.  
File no.: 0000001352  
Facility Id No.: 184284

Dear Applicant:

We are currently processing the above captioned application. Our preliminary analysis indicates the following:

The tower determination study results based on the tower engineering specification of the above referenced construction permit show that the tower requires registration with the FAA because the tower heights as specified failed slope with two runways at Akron Fulton International Airport.

The tower determination study is imported below for your reference:

| <b>DETERMINATION Results</b>  |     |              |               |                   |                  |                      |                    |
|---|-----|--------------|---------------|-------------------|------------------|----------------------|--------------------|
| <b>PASS SLOPE(50:1): NO FAA REQ-RWY 10499 MTRS OR LESS &amp; 4097.73 MTRS (4.09769 ) KM AWAY</b>                |     |              |               |                   |                  |                      |                    |
| Type  | C/R | Latitude     | Longitude     | Name              | Address          | Lowest Elevation (m) | Runway Length (m)  |
| AIRP  | R   | 40-59-33.00N | 081-25-39.00W | MAYFIELD          | SUMMIT AKRON, OH | 332.8                | 705.60000000000002 |
| <b>FAIL SLOPE (100:1)FAA REQ - 5072.0 Meters(16640.2 Feet) away &amp; exceeds by 9.0 Meters (29.5300 Feet)</b>  |     |              |               |                   |                  |                      |                    |
| Type  | C/R | Latitude     | Longitude     | Name              | Address          | Lowest Elevation (m) | Runway Length (m)  |
| AIRP  | R   | 41-02-4.00N  | 081-27-54.00W | AKRON FULTON INTL | SUMMIT AKRON, OH | 318.0                | 1931.2             |
| <b>FAIL SLOPE (100:1)FAA REQ - 4687.0 Meters(15377.1 Feet) away &amp; exceeds by 13.0 Meters (42.6499 Feet)</b> |     |              |               |                   |                  |                      |                    |
| Type  | C/R | Latitude     | Longitude     | Name              | Address          | Lowest Elevation (m) | Runway Length (m)  |
| AIRP  | R   | 41-02-29.00N | 081-27-27.00W | AKRON FULTON INTL | SUMMIT AKRON, OH | 318.0                | 1931.2             |

| <b>Your Specifications</b>     |                  |
|--------------------------------|------------------|
| <b>NAD83 Coordinates</b>       |                  |
| Latitude                       | 41-01-32.0 north |
| Longitude                      | 081-24-21.0 west |
| <b>Measurements (Meters)</b>   |                  |
| Overall Structure Height (AGL) | 18               |
| Support Structure Height (AGL) | 18               |
| Site Elevation (AMSL)          | 360              |
| <b>Structure Type</b>          |                  |
| MAST - Mast                    |                  |

If you do not amend your application electronically within 30 days from the date of this letter to resolve the above deficiency, we will dismiss your application.

Sincerely

Hossein Hashemzadeh  
Deputy Chief  
Video Division  
Media Bureau

C.c. DTV America II, LLC  
C/O – Kristina Bruni  
Bella Spectra Corporation  
1671 NW 144<sup>th</sup> Terrace, Suite 110  
Sunrise, FL. 33323