



Federal Communications Commission  
Washington, D.C. 20554

June 18, 2015

DTV America II, LLC  
12717 W Sunrise Blvd., Suite 372  
Sunrise, FL. 33323

1800E3-RLG

In re: Low Power Television Application of:  
DTV America II, LLC  
Channel 43, Canton, OH.  
File no.: 0000001352  
Facility Id No.: 184284

Dear Applicant:

On May 12, 2015, the licensee as addressed above was sent a 30 day deficiency letter as outlined below:

The tower determination study results based on the tower engineering specification of the above referenced construction permit show that the tower requires registration with the FAA because the tower heights as specified failed slope with two runways at Akron Fulton International Airport.

The tower determination study is imported below for your reference:

<b>DETERMINATION Results</b>							
<b>PASS SLOPE(50:1): NO FAA REQ-RWY 10499 MTRS OR LESS &amp; 4097.73 MTRS (4.09769 ) KM AWAY</b>							
Type	C/R	Latitude	Longitude	Name	Address	Lowest Elevation (m)	Runway Length (m)
AIRP	R	40-59-33.00N	081-25-39.00W	MAYFIELD	SUMMIT AKRON, OH	332.8	705.60000000000002
<b>FAIL SLOPE (100:1)FAA REQ - 5072.0 Meters(16640.2 Feet) away &amp; exceeds by 9.0 Meters (29.5300 Feet)</b>							
Type	C/R	Latitude	Longitude	Name	Address	Lowest Elevation (m)	Runway Length (m)
AIRP	R	41-02-4.00N	081-27-54.00W	AKRON FULTON INTL	SUMMIT AKRON, OH	318.0	1931.2
<b>FAIL SLOPE (100:1)FAA REQ - 4687.0 Meters(15377.1 Feet) away &amp; exceeds by 13.0 Meters (42.6499 Feet)</b>							
Type	C/R	Latitude	Longitude	Name	Address	Lowest Elevation (m)	Runway Length (m)
AIRP	R	41-02-29.00N	081-27-27.00W	AKRON FULTON INTL	SUMMIT AKRON, OH	318.0	1931.2

<b>Your Specifications</b>	
<b>NAD83 Coordinates</b>	
Latitude	41-01-32.0 north
Longitude	081-24-21.0 west
<b>Measurements (Meters)</b>	
Overall Structure Height (AGL)	18
Support Structure Height (AGL)	18
Site Elevation (AMSL)	360
<b>Structure Type</b>	
MAST - Mast	

If you do not amend your application electronically within 30 days from the date of this letter to resolve the above deficiency, we will dismiss your application.

Our records show that no amendment has been filed as of June 18, 2015, to resolve the deficiency issue as indicated above; therefore, the above referenced application IS HEREBY DISMISSED.

Sincerely

Hossein Hashemzadeh  
Deputy Chief  
Video Division  
Media Bureau

C.c. DTV America II, LLC  
C/O – Kristina Bruni  
Bella Spectra Corporation  
1671 NW 144<sup>th</sup> Terrace, Suite 110  
Sunrise, FL. 33323